

DISPLAY INSTRUCTIONS





STEP ONE

First take the 1A rotator place it down flat. Then grab all three 2A sides and engage them down into the rotator. Then at the tops of the 2A sides, take 3A and engage it down, then take all three 4A headers and engage them down into 3A as seen in the photo.